



Mercedes c: 1GEG131

Vinnumber:	WDD2052041F212549	Versionname:	
First Registrationdate:	15/06/2015	Fiscalpower:	
Expertise Mileage:	185289	Power Kw:	120
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3823
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Type of headlighting	Tow bar removable
Type of GPS	Headlighting LED
Type of Lining	GPS big screen color
Type of climate control	Lining artificial leather
	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/50/17/98 W LightMetal			
	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 0 mm	Re.R.	Bridgestone: 0 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1140,80
-------------------	----------------

Windscreen, Repaired, Acceptable	0,00
----------------------------------	-------------



Bumper F, Scratch(es), LI - Repair and paint (complete)		211,80
		
		
Tailgate, Scratch(es), Acceptable		0,00
No pictures to display		
Tyre F L, Out of tolerance, E - Replace		132,00
		
		
Interior, Dirty, Cleaning		50,00
		
		
Alloy rim F L polished, Rust, Acceptable		0,00
No pictures to display		
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)		308,20
		
Roof, Not original part, Acceptable		0,00
		
Rearview mirror housing L, Scratch(es), Acceptable		0,00
No pictures to display		
Tyre F R, Out of tolerance, E - Replace		132,00
		
		
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Bonnet, Not original part, Acceptable	0,00
---------------------------------------	------

