



BMW 2 GRAN TOURER: 1LRH015

Vinnumber:	WBA2E310005C01782	Versionname:	1.5 216D GRAN TOURER
First Registrationdate:	13/11/2015	Fiscalpower:	
Expertise Mileage:	142239	Power Kw:	85
Bodytype:	MPV	Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1731
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1695,56
Door R R, Bad repair, Acceptable	0,00



Wing R L, Chemical polution, 67 - Polish	0,00
--	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display


Bonnet, Chemical polution, LI - Repair and paint (complete)	338,08
---	--------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------




Roof, Chemical polution, LI - Repair and paint (complete)	553,00
---	--------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------





Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18




Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Dent(s), PDR - Paintless dent repair

63,00



Bumper F, Scratch(es), 67 - Polish

0,00

No pictures to display

Bumper grille, Deformed / Strained, Forfeit

24,00



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display