


BMW X3: 1NBC551

Vinnumber:	WBAWZ510000L23778	Versionname:	2.0 XDRIVE20D (120KW) 4WD
First Registrationdate:	8/01/2016	Fiscalpower:	
Expertise Mileage:	181662	Power Kw:	120
Bodytype:		Body color	Silver
Gearbox:	Automatic	Paint type	Metalic
Transmission:	4 Wheel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1409
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/60/17/99 V LightMetal			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Kleber: 4 mm	Re.R.	Kleber: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	126,00
Bonnet, Stone chip(s), Acceptable	0,00



Bumper F, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Door F R, Dent(s), PDR - Paintless dent repair	63,00
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Dent(s), PDR - Paintless dent repair	63,00
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F M, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	