


RENAULT CLIO: 1LLD587

Vinnumber:	VF15R0J0A53834410	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	19/10/2015	Fiscalpower:	
Expertise Mileage:	119068	Power Kw:	66
Bodytype:		Body color	Silver
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3232
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/18/92 T Steel			
Winter tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	No	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2277,28
Tyre repair kit, Missing, E - Replace	168,42



Door F L, Scratch(es), LI - Repair and paint (complete)

254,68



Wheel cover F R, Missing, E - Replace

24,00



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display



Wing R L, Scratch(es), LI - Repair and paint (complete)

246,56



Bonnet, Chemical polution, LI - Repair and paint (complete)

232,06




Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

294,56



Wheel cover R R, Scratch(es), E - Replace

24,00



Roof, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace

24,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Door moulding Lower R R, Scratch(es), E - Replace

96,00



Floor covering F L, Hole, Smart repair

64,32





Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Wheel cover R L, Scratch(es), E - Replace

24,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Door R R, Scratch(es), LI - Repair and paint (complete)

254,68



