



VOLVO V60: 1KPZ730

Vinnumber:	YV1GWDCH0G1289113	Versionname:	2.4 PLUG-IN HYBRID D6 MOMENTUM
First Registrationdate:	12/06/2015	Fiscalpower:	
Expertise Mileage:	61929	Power Kw:	162
Bodytype:		Body color	Burgundy
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Hybrid Diesel	Oil level	OK
Maintenance	23056	Parking lot	3622
Maintenance	7 MAAND		
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	235/45/17/97 Y LightMetal			
	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	2		
Number of charging cables (rapid charge)	1		

Total cost ex VAT	425,20
Door panel R R, Scratch(es), Acceptable	0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F R, Scratch(es), E - Replace	235,20
---	--------



Wing R L, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Wing F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Ceiling, Stain, Acceptable	0,00
----------------------------	------

No pictures to display


Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Internal Boot Lining R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Roof, Scratch(es), 67 - Polish	0,00
--------------------------------	------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display