













No Tow bar

ALEA	ROMEO	CHILLIA.	AL 444
ALFA	ROMEO	GIULIA:	AL411

Vinnumber:	ZAREAEGN5J7587599	Versionname:	2.0 206kW Veloce
First Registrationdate:	25/04/2018	Fiscalpower:	
Expertise Mileage:	46700	Power Kw:	206
Bodytype:		Body color	Red
Gearbox:	Automatic	Paint type	Metalic
Transmission:	4 Weel	Rims summer	Aluminium
Fueltype:	Petrol	Oil level	ОК
Maintenance	GEEN MELDING	Parking lot	2108
Maintenance	ОК		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		

ок

Options

Oil level

Registration Certificate Car (BE)

GPS storage Seats electric F L HD GPS storage Seats electric F R Windows electric F Sun Roof electric Windows electric R Panoramic roof Cruise Control Central consol F Steering wheel multifunctional Front parking sensors Seats F heated Rear parking sensors Radio multimedia Type of Tow bar

Type of headlighting Headlighting Xenon
Type of GPS GPS big screen color
Type of Lining Lining leather
Type of climate control Autom climate control

Adaptive cruise control

Sport seats

Limited Technical Inspection

Airco functioning	ок	Battery functioning	Yes
Tires wear profile	ок	Power steering	Yes
Idle position	ок	Sound engine	ок
Engine startingtime	ок	Clutch test	ок
Exhaust gass	ок	Wiper fluid level	ок
Handbrake	ок	Transmission	ок
		Lighting	ок
		Wiperblades	ОК

Degree of wear

Summer tyres:

225/45/1	18/91 W LightMetal	520	20 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 -
Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	562,44
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00









Alloy rim R R, Scratch(es), E - Replace

277,44









Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00







Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



