



BMW 4 GRAN COUPE: QZ5534

Vinnumber:	WBA4D31020G767679	Versionname:	2.0 420i (135KW) GRAN COUPE
First Registrationdate:	8/11/2016	Fiscalpower:	
Expertise Mileage:	28759	Power Kw:	135
Bodytype:		Body color	Blue
Gearbox:	Automatic	Paint type	Metallic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Petrol	Oil level	OK
Maintenance	OK	Parking lot	3214
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	225/50/17/92 MS LightMetal			
	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1321,44
Bumper R, Scratch(es), Acceptable			0,00
No pictures to display			
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)			393,84



Bumper F L, Scratch(es), It - Spot repair	115,56
---	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R L, Dent(s), LI - Repair and paint (complete)	430,02
---	--------



Door F R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------

