


MERCEDES A: 1PRR335

Vinnumber:	WDD1760121J516973	Versionname:	A 180 d BlueEFFICIENCY Edition
First Registrationdate:	31/08/2016	Fiscalpower:	
Expertise Mileage:	72099	Power Kw:	80
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	LKW1
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F	
GPS storage	Type of Tow bar	No Tow bar
GPS storage	SD	
Windows electric F		
Windows electric R		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	195/65/15/95 V Steel			
	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1328,76
Sill outer R, Deformed / Strained, Forfeit			24,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Bad repair, Acceptable

0,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Interior, Dirty, Chemical cleaning

150,00



Wheel cover R R, Scratch(es), E - Replace

30,00



Wheel cover F R, Scratch(es), E - Replace

30,00



Bumper F, Broken, LI - Repair and paint (complete)

283,80





Wheel cover F L, Scratch(es), E - Replace	30,00
---	-------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)	139,56
---	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rear panel, Deformed / Strained, Forfeit	39,60
--	-------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Luggage space cover, Missing, E - Replace	240,00
---	--------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display