



BMW 5 TOURING: 1KKV233

Vinnumber:	WBA5L11030D969394	Versionname:	2.0 518D (100KW) TOURING
First Registrationdate:	22/05/2015	Fiscalpower:	
Expertise Mileage:	159958	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4825
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	Tow bar fixed
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/55/17/97 Y LightMetal			
	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	174,00
--------------------------	---------------

Bumper F, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Airvent mid dashboard, Broken, F, Replace	474,00
--	---------------

