


**MERCEDES CLA SHOOTING BRAKE: 1LAE462**

|                                   |                                 |              |                                       |
|-----------------------------------|---------------------------------|--------------|---------------------------------------|
| Vinnumber:                        | <b>WDD1179081N254675</b>        | Versionname: | <b>2.1 CLA 200 CDI SHOOTING BRAKE</b> |
| First Registrationdate:           | <b>30/07/2015</b>               | Fiscalpower: |                                       |
| Expertise Mileage:                | <b>80390</b>                    | Power Kw:    | <b>100</b>                            |
| Bodytype:                         |                                 | Body color   | <b>Grey</b>                           |
| Gearbox:                          | <b>MAN 6 VIT</b>                | Paint type   | <b>Metalic</b>                        |
| Transmission:                     | <b>Front</b>                    | Rims summer  | <b>Aluminium</b>                      |
| Fueltype:                         | <b>Diesel</b>                   | Oil level    | <b>OK</b>                             |
| Maintenance                       | <b>NOT OK</b>                   | Parking lot  | <b>3725</b>                           |
| Maintenance                       | <b>VERSTREKEN. B5 UITVOEREN</b> |              |                                       |
| Battery functioning               | <b>Yes</b>                      |              |                                       |
| Number of doors                   | <b>5</b>                        |              |                                       |
| Number of seats                   | <b>5</b>                        |              |                                       |
| Number head rests                 | <b>1</b>                        |              |                                       |
| Rims summer                       | <b>Aluminium</b>                |              |                                       |
| Category                          | <b>Passenger Car</b>            |              |                                       |
| Oil level                         | <b>OK</b>                       |              |                                       |
| Registration Certificate Car (BE) | <b>Yes</b>                      |              |                                       |

**Options**

|                                |                               |                       |                   |
|--------------------------------|-------------------------------|-----------------------|-------------------|
| Radio CD                       |                               | Central consol F      |                   |
| GPS storage                    | <b>SD</b>                     | Luggage cover         |                   |
| GPS storage                    |                               | Front parking sensors |                   |
| Windows electric F             |                               | Rear parking sensors  |                   |
| Windows electric R             |                               | Type of Tow bar       | <b>No Tow bar</b> |
| Cruise Control                 |                               |                       |                   |
| Steering wheel multifunctional |                               |                       |                   |
| Radio multimedia               |                               |                       |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>   |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>   |                       |                   |
| Type of Lining                 | <b>Lining semi-leather</b>    |                       |                   |
| Type of climate control        | <b>Manual climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/55/16/91 H LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|               | Re.L.                            | <b>Michelin: 7 mm</b> | Re.R. | <b>Michelin: 7 mm</b> |

**Assistance equipment**

|                                                              |            |            |                |
|--------------------------------------------------------------|------------|------------|----------------|
| Repair kit                                                   | <b>Yes</b> | Compressor | <b>Yes</b>     |
| Total cost ex VAT                                            |            |            | <b>2019,63</b> |
| Interior, Smell, Ozone treatment                             |            |            | <b>152,58</b>  |
| <i>No pictures to display</i>                                |            |            |                |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) |            |            | <b>95,00</b>   |



Bumper F, Scratch(es), It - Spot repair

115,56




Floor covering F L, Burned, E - Replace

252,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

235,80



Wing R R, Repaired, Acceptable

0,00



Maintenance, Maintenance, Execute

0,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

332,20



Seat cover R L, Stain, Cleaning

25,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

358,50





|                                                                     |        |
|---------------------------------------------------------------------|--------|
| Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 342,35 |
|---------------------------------------------------------------------|--------|



|                                                    |        |
|----------------------------------------------------|--------|
| Covering interior A pillar L, Burned, Smart repair | 110,64 |
|----------------------------------------------------|--------|



|                           |      |
|---------------------------|------|
| Roof, Dent(s), Acceptable | 0,00 |
|---------------------------|------|

