



PEUGEOT Boxer 330: 1CFX041

Vinnumber:	VF3YBUMFC12108732	Versionname:	BOXER 333 B/F LWB L3H2 FAP 150PK
First Registrationdate:	16/11/2011	Fiscalpower:	
Expertise Mileage:	172874	Power Kw:	110
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	LCV03
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining semi-artificial leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/70/15/109 MS Steel				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 1911,40

Interior, Damaged, Acceptable 0,00





Mirror side blinker R, Broken, E - Replace

28,50



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Trunk door panel R, Broken, E - Replace

62,00



Wing R L, Dent(s), LI - Repair and paint (complete)

231,15



Trunk door panel L, Broken, E - Replace

62,00



Bumper F R, Broken, Smart repair

110,64



Grill frame, Broken, E - Replace

49,40



Engine protective plate, Broken, E - Replace

62,00



Seat cover F L, Worn, Acceptable

0,00

No pictures to display

Wing trim R R, Broken, E - Replace

69,00



Door F L, Dent(s), LI - Repair and paint (complete)

238,76



Separation wall, Dent(s), Acceptable

0,00



Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete)

454,02



Bumper F L, Broken, Smart repair

110,64



Bumper cover R M, Broken, Smart repair

110,64



Door moulding Lower R R, Missing, E - Replace

91,50

