


**VOLKSWAGEN TOURAN: 1NAN641**

Vinnumber:	WVGZZZ1TZGW539571	Versionname:	2.0 TDI SCR 110KW BMT HIGHLINE
First Registrationdate:	5/01/2016	Fiscalpower:	
Expertise Mileage:	56909	Power Kw:	110
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2506
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

**Options**

Windows electric F	Seats R heated
Windows electric R	Sun Roof electric
Cruise Control	Panoramic roof
Steering wheel multifunctional	Central consol F
Seats F heated	Luggage cover
Radio multimedia	Front parking sensors
Type of headlighting	Rear parking sensors
Type of GPS	
Type of Lining	
Type of climate control	

**Headlighting LED**  
**GPS big screen color**  
**Lining semi-Alcantara**  
**Autom climate control**

**Limited Technical Inspection**

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

**Degree of wear**

	<b>205/60/16/92 MS LightMetal</b>			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

**Assistance equipment**

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1268,89
Bumper F L, Scratch(es), It - Spot repair			115,56



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Interior, Dirty, Cleaning

150,00



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Dent(s), LI - Repair and paint (complete)

220,18



Wing R R, Dent(s), PDR - Paintless dent repair

63,00

