



RENAULT CLIO: 1LUU028

Vinnumber:	VF15R0J0A54168195	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	10/12/2015	Fiscalpower:	
Expertise Mileage:	57507	Power Kw:	66
Bodytype:		Body color	Red
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3832
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 T Steel			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1205,66
-------------------	---------

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Stone chip(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

No pictures to display

Instrument panel cover, Worn, Acceptable	0,00
--	------



Bumper R, Dent(s) and scratch(es), Le - Replace and paint	535,20
---	--------



Roof, Dent(s), Acceptable	0,00
---------------------------	------

No pictures to display

Wheel cover R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Wheel cover F R, Scratch(es), E - Replace	24,00
---	-------



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)	115,56
---	--------



Wheel cover R R, Scratch(es), E - Replace	24,00
---	-------





Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

241,34



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Wheel cover F L, Scratch(es), E - Replace

24,00



Wing R R, Scratch(es), 67 - Polish

0,00

No pictures to display

Wing R L, Dent(s), PDR - Paintless dent repair

63,00

