



RENAULT CLIO GRANDTOUR: 1RAE181

Vinnumber:	VF17RKJ0A56441599	Versionname:	1.5 ENERGY DCI 90 EXPRESSION
First Registrationdate:	25/10/2016	Fiscalpower:	
Expertise Mileage:	147272	Power Kw:	66
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	PARKING KT
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/55/16/91 H Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			918,77
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)			217,44



Bonnet, Chemical polution, LI - Repair and paint (complete)

280,06



Ignition key, Missing, E - Replace

150,00



Rear window, Not original part, Remove lettering

0,00



Wheel cover R R, Scratch(es), E - Replace

24,00



Wheel cover F L, Broken, E - Replace

24,00



Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper corner R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel arch cover F R, Deformed / Strained, E - Replace

75,27



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Tailgate, Scratch(es) and dent(s), LI

0,00

Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	
Interior, Stain, Cleaning	100,00
	
Wheel cover R L, Scratch(es), E - Replace	24,00
	
Wing R R, Dent(s) and scratch(es), Le - Replace and paint	0,00
	
Wheel cover F R, Scratch(es), E - Replace	24,00
	
Wing R L, Dent(s), Acceptable	0,00
No pictures to display	
Central pillar R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper spoiler F, Scratch(es), Acceptable	0,00
No pictures to display	
Wing F R, Scratch(es), Acceptable	0,00
No pictures to display	