


**BMW 5 TOURING: 1PTR681**

|                                   |                          |              |                                 |
|-----------------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber:                        | <b>WBA5L11050G718018</b> | Versionname: | <b>2.0 518D (110KW) TOURING</b> |
| First Registrationdate:           | <b>15/09/2016</b>        | Fiscalpower: |                                 |
| Expertise Mileage:                | <b>176418</b>            | Power Kw:    | <b>110</b>                      |
| Bodytype:                         |                          | Body color   | <b>Grey</b>                     |
| Gearbox:                          | <b>Automatic</b>         | Paint type   | <b>Metalic</b>                  |
| Transmission:                     | <b>Back</b>              | Rims summer  | <b>Aluminium</b>                |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                       |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>4704</b>                     |
| Number of doors                   | <b>5</b>                 |              |                                 |
| Number of seats                   | <b>5</b>                 |              |                                 |
| Number head rests                 | <b>5</b>                 |              |                                 |
| Rims summer                       | <b>Aluminium</b>         |              |                                 |
| Category                          | <b>Passenger Car</b>     |              |                                 |
| Oil level                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                 |

**Options**

|                                |                              |                       |
|--------------------------------|------------------------------|-----------------------|
| Radio CD                       |                              | Central consol F      |
| GPS storage                    | <b>HD</b>                    | Luggage cover         |
| GPS storage                    |                              | Front parking sensors |
| Windows electric F             |                              | Rear parking sensors  |
| Windows electric R             |                              |                       |
| Cruise Control                 |                              |                       |
| Steering wheel multifunctional |                              |                       |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |
| Type of Lining                 | <b>Lining leather</b>        |                       |
| Type of climate control        | <b>Autom climate control</b> |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>225/55/17/97 H LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|               | Re.L.                            | <b>Michelin: 3 mm</b> | Re.R. | <b>Michelin: 3 mm</b> |

**Assistance equipment**

|                                                              |            |            |                |
|--------------------------------------------------------------|------------|------------|----------------|
| Repair kit                                                   | <b>Yes</b> | Compressor | <b>Yes</b>     |
| Total cost ex VAT                                            |            |            | <b>1396,06</b> |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) |            |            | <b>95,00</b>   |



Side window trim F R, Deformed / Strained, E - Replace

58,10



Bumper R, Deformed / Strained, Le - Replace and paint

766,80



Bumper F, Scratch(es), LI - Repair and paint (complete)

326,16



Ignition key, Missing, E - Replace

150,00

No pictures to display

Rear window, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display