



BMW 3 TOURING: 1LSJ167

Vinnumber:	WBA8L710X0K556111	Versionname:	2.0 316D (85KW) TOURING
First Registrationdate:	23/11/2015	Fiscalpower:	
Expertise Mileage:	188695	Power Kw:	85
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4123
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/92 V LightMetal			
	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Total cost ex VAT	612,88
Rear window, Scratch(es), Acceptable	0,00
No pictures to display	
Armrest L, Deformed / Strained, Acceptable	0,00
No pictures to display	
Door R L, Dent(s), PDR - Paintless dent repair	63,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	259,80
---	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08
---	--------

