


**BMW 2 ACTIVE TOURER: QE6449**

|                                   |                          |              |                                       |
|-----------------------------------|--------------------------|--------------|---------------------------------------|
| Vinnumber:                        | <b>WBA2C11080VZ57626</b> | Versionname: | <b>2.0 218D (110KW) ACTIVE TOURER</b> |
| First Registrationdate:           | <b>8/04/2015</b>         | Fiscalpower: |                                       |
| Expertise Mileage:                | <b>132011</b>            | Power Kw:    | <b>110</b>                            |
| Bodytype:                         |                          | Body color   | <b>Blue</b>                           |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>                        |
| Transmission:                     | <b>Back</b>              | Rims summer  | <b>Aluminium</b>                      |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                             |
| Maintenance                       | <b>OK</b>                | Parking lot  | <b>1524</b>                           |
| Battery functioning               | <b>Yes</b>               |              |                                       |
| Number of doors                   | <b>5</b>                 |              |                                       |
| Number of seats                   | <b>5</b>                 |              |                                       |
| Number head rests                 | <b>5</b>                 |              |                                       |
| Rims summer                       | <b>Aluminium</b>         |              |                                       |
| Category                          | <b>Passenger Car</b>     |              |                                       |
| Oil level                         | <b>OK</b>                |              |                                       |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                       |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Windows electric F             | Sun Roof electric            |
| Windows electric R             | Panoramic roof               |
| Cruise Control                 | Central consol F             |
| Steering wheel multifunctional | Luggage cover                |
| Seats F heated                 | Front parking sensors        |
| Radio multimedia               | Rear parking sensors         |
| Type of headlighting           | <b>Headlighting LED</b>      |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                   |                          |       |                          |
|---------------|-----------------------------------|--------------------------|-------|--------------------------|
|               | <b>205/55/17/92 MS LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                             | <b>Bridgestone: 5 mm</b> | Fr.R. | <b>Bridgestone: 5 mm</b> |
|               | Re.L.                             | <b>Bridgestone: 6 mm</b> | Re.R. | <b>Bridgestone: 6 mm</b> |

**Assistance equipment**

|                                                                       |            |            |                |
|-----------------------------------------------------------------------|------------|------------|----------------|
| Repair kit                                                            | <b>Yes</b> | Compressor | <b>Yes</b>     |
| Total cost ex VAT                                                     |            |            | <b>1067,76</b> |
| Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) |            |            | <b>95,00</b>   |



Bumper F L, Dent(s) and scratch(es), It - Spot repair

115,56



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), E - Replace

370,00



Windscreen, Stone chip(s), E - Replace

487,20



Door R L, Scratch(es), Acceptable

0,00

No pictures to display