



OPEL INSIGNIA: 1LJK133

Vinnumber:	W0LGM6E26G1015623	Versionname:	1.6 CDTI 88KW S/S EDITION
First Registrationdate:	5/10/2015	Fiscalpower:	
Expertise Mileage:	197811	Power Kw:	88
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3120
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/92 MS LightMetal			
Winter tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm


Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1439,56
Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)			373,68



Roof, Hail damage, PDR - Hail

125,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Windscreen, Stone chip(s), Windscreen repair

58,80



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Backrest cover F L, Damaged, Acceptable

0,00



Seat cover F L, Damaged, Acceptable

0,00



Bonnet, Chemical polution, LI - Repair and paint (complete)

362,08

