



VOLVO XC60: 1HZE010

Vinnumber:	YV1DZ31A1F2687462	Versionname:	2.0 D3 2WD KINETIC
First Registrationdate:	4/11/2014	Fiscalpower:	
Expertise Mileage:	103398	Power Kw:	100
Bodytype:		Body color	White
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3629
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	Type of Tow bar
Type of headlighting	No Tow bar
Type of GPS	Headlighting Halogen
Type of Lining	GPS big screen color
Type of climate control	Lining leather
	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/104 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1097,72
-------------------	----------------

Sill outer L, Scratch(es), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	---------------



Bodywork, Not original part, Acceptable	0,00
No pictures to display	
Protection plate M, Deformed / Strained, E - Replace	74,00



Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Door R R, Scratch(es), It - Spot repair	115,56
---	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display	
Bumper F, Scratch(es), LI - Repair and paint (complete)	284,16

