



# NISSAN X-Trail: 1JEP767

|                                    |                   |              |                                |
|------------------------------------|-------------------|--------------|--------------------------------|
| Vinnumber:                         | JN1TCNT32U0001476 | Versionname: | X-TRAIL 4WD Connect Edit.130PK |
| First Registrationdate:            | 26/11/2014        | Fiscalpower: |                                |
| Expertise Mileage:                 | 82215             | Power Kw:    | 96                             |
| Bodytype:                          |                   | Body color:  | White                          |
| Gearbox:                           | MAN 6 VIT         | Paint type:  | Metalic                        |
| Transmission:                      | 4 Weel            | Rims summer: | Aluminium                      |
| Fueltype:                          | Diesel            | Oil level:   | OK                             |
| Battery functioning:               | Yes               | Parking lot: | 1407                           |
| Number of doors:                   | 5                 |              |                                |
| Number of seats:                   | 5                 |              |                                |
| Number head rests:                 | 5                 |              |                                |
| Rims summer:                       | Aluminium         |              |                                |
| Category:                          | Passenger Car     |              |                                |
| Oil level:                         | OK                |              |                                |
| Registration Certificate Car (BE): | Yes               |              |                                |

## Options

|                                |                       |
|--------------------------------|-----------------------|
| Radio CD                       | Sun Roof electric     |
| Windows electric F             | Panoramic roof        |
| Windows electric R             | Central consol F      |
| Cruise Control                 | Luggage cover         |
| Steering wheel multifunctional | Front parking sensors |
| Radio multimedia               | Rear parking sensors  |
| Type of headlighting           | Type of Tow bar       |
| Type of GPS                    |                       |
| Type of Lining                 |                       |
| Type of climate control        |                       |
| Headlighting Halogen           |                       |
| GPS big screen color           |                       |
| Lining fabrics                 |                       |
| Autom climate control          |                       |
|                                | Tow bar removable     |

## Limited Technical Inspection

|                     |    |                     |     |
|---------------------|----|---------------------|-----|
| Airco functioning   | OK | Battery functioning | Yes |
| Tires wear profile  | OK | Power steering      | Yes |
| Idle position       | OK | Sound engine        | OK  |
| Engine startingtime | OK | Clutch test         | OK  |
| Exhaust gass        | OK | Wiper fluid level   | OK  |
| Handbrake           | OK | Transmission        | OK  |
|                     |    | Lighting            | OK  |
|                     |    | Wiperblades         | OK  |

## Degree of wear

|               |                           |            |       |            |
|---------------|---------------------------|------------|-------|------------|
|               | 225/55/19/99 V LightMetal |            |       |            |
| Winter tyres: | Fr.L.                     | Toyo: 4 mm | Fr.R. | Toyo: 4 mm |
|               | Re.L.                     | Toyo: 4 mm | Re.R. | Toyo: 4 mm |

## Assistance equipment

|                                          |     |      |     |
|------------------------------------------|-----|------|-----|
| Emergency spare wheel                    | Yes | Jack | Yes |
| Number of charging cables (normal)       | 0   |      |     |
| Number of charging cables (rapid charge) | 0   |      |     |

|                                                                       |        |
|-----------------------------------------------------------------------|--------|
| Total cost ex VAT                                                     | 698,32 |
| Wing R R, Scratch(es), Acceptable                                     | 0,00   |
| No pictures to display                                                |        |
| Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) | 95,00  |



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R polished, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16

