



**MITSUBISHI ASX: 1JKK542**

|                                   |                   |              |                                        |
|-----------------------------------|-------------------|--------------|----------------------------------------|
| Vinnumber:                        | JMBXJGA6WFZ405894 | Versionname: | 1.8 DI-D LP CLEARTEC ANNIV. ED. II 2WD |
| First Registrationdate:           | 9/01/2015         | Fiscalpower: |                                        |
| Expertise Mileage:                | 50023             | Power Kw:    | 85                                     |
| Bodytype:                         |                   | Body color   | Grey                                   |
| Gearbox:                          | MAN 6 VIT         | Paint type   | Metallic                               |
| Transmission:                     | Front             | Rims summer  | Aluminium                              |
| Fueltype:                         | Diesel            | Oil level    | OK                                     |
| Battery functioning               | Yes               | Parking lot  | 1117                                   |
| Number of doors                   | 5                 |              |                                        |
| Number of seats                   | 5                 |              |                                        |
| Number head rests                 | 5                 |              |                                        |
| Rims summer                       | Aluminium         |              |                                        |
| Category                          | Passenger Car     |              |                                        |
| Oil level                         | OK                |              |                                        |
| Registration Certificate Car (BE) | Yes               |              |                                        |

**Options**

|                                |                       |                      |               |
|--------------------------------|-----------------------|----------------------|---------------|
| GPS storage                    | HD                    | Panoramic roof       |               |
| GPS storage                    |                       | Central consol F     |               |
| Windows electric F             |                       | Luggage cover        |               |
| Windows electric R             |                       | Rear parking sensors |               |
| Cruise Control                 |                       | Type of Tow bar      | Tow bar fixed |
| Steering wheel multifunctional |                       |                      |               |
| Radio multimedia               |                       |                      |               |
| Type of headlighting           | Headlighting Halogen  |                      |               |
| Type of GPS                    | GPS big screen color  |                      |               |
| Type of Lining                 | Lining fabrics        |                      |               |
| Type of climate control        | Autom climate control |                      |               |

**Limited Technical Inspection**

|                     |    |                     |     |
|---------------------|----|---------------------|-----|
| Airco functioning   | OK | Battery functioning | Yes |
| Tires wear profile  | OK | Power steering      | Yes |
| Idle position       | OK | Sound engine        | OK  |
| Engine startingtime | OK | Clutch test         | OK  |
| Exhaust gass        | OK | Wiper fluid level   | OK  |
| Handbrake           | OK | Transmission        | OK  |
|                     |    | Lighting            | OK  |
|                     |    | Wiperblades         | OK  |

**Degree of wear**

|               |                           |                |       |                |
|---------------|---------------------------|----------------|-------|----------------|
|               | 215/60/17/96 H LightMetal |                |       |                |
| Winter tyres: | Fr.L.                     | Uniroyal: 5 mm | Fr.R. | Uniroyal: 5 mm |
|               | Re.L.                     | Uniroyal: 5 mm | Re.R. | Uniroyal: 5 mm |

**Assistance equipment**

|                                          |     |            |     |
|------------------------------------------|-----|------------|-----|
| Repair kit                               | Yes | Compressor | Yes |
| Number of charging cables (normal)       | 0   |            |     |
| Number of charging cables (rapid charge) | 0   |            |     |

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 190,00 |
|-------------------|--------|

|                               |      |
|-------------------------------|------|
| Wing R R, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

|                                                                       |       |
|-----------------------------------------------------------------------|-------|
| Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|-----------------------------------------------------------------------|-------|



|                                                                       |       |
|-----------------------------------------------------------------------|-------|
| Door F L, Dent(s), Acceptable                                         | 0,00  |
| <i>No pictures to display</i>                                         |       |
| Door F R, Scratch(es), Acceptable                                     | 0,00  |
| <i>No pictures to display</i>                                         |       |
| Door R R, Dent(s), Acceptable                                         | 0,00  |
| <i>No pictures to display</i>                                         |       |
| Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |



|                                                 |      |
|-------------------------------------------------|------|
| Roof, Scratch(es), Acceptable                   | 0,00 |
| <i>No pictures to display</i>                   |      |
| Door R R, Scratch(es), Acceptable               | 0,00 |
| <i>No pictures to display</i>                   |      |
| Door F R, Dent(s), Acceptable                   | 0,00 |
| <i>No pictures to display</i>                   |      |
| Bonnet, Stone chip(s), Acceptable               | 0,00 |
| <i>No pictures to display</i>                   |      |
| Alloy rim R R polished, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>                   |      |