



VOLKSWAGEN SHARAN: 1KPX911

Vinnumber:	WVWZZZ7NZFV048160	Versionname:	2.0 CR TDI 103KW HIGHLINE BMT
First Registrationdate:	12/06/2015	Fiscalpower:	
Expertise Mileage:	169696	Power Kw:	103
Bodytype:		Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	21.000 KM OU 650 JOURS	Parking lot:	3116
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 H LightMetal				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	420,46
-------------------	---------------

Sliding door R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Outer door handle F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Reflector, Broken, E - Replace

39,10



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Door F L, Dent(s), Acceptable

0,00

No pictures to display

Mirror side blinker L, Broken, E - Replace

31,20



Bumper F, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

350,16



Wing F R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display