



OPEL Zafira: 1HKL209			
Vinnumber:	W0LPE9E3XE2098164	Versionname:	ZAFIRA TOURER ecoFL.Cosmo S/S 136PK
First Registrationdate:	11/08/2014	Fiscalpower:	
Expertise Mileage:	152747	Power Kw:	100
Bodytype:	MPV	Body color	Dark Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	130482 KM	Parking lot	4426
Maintenance	OK		
Maintenance	22-5-2019		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	225/50/17/98 V LightMetal			
	Fr.L.	Uniroyal: 8 mm	Fr.R.	Uniroyal: 8 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1338,35
Door F L, Scratch(es), Acceptable			0,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00



Rearlight L, Broken, E - Replace

114,00



Door frame R R, Dent(s), Acceptable

0,00



Seat cover F L, Stain, Cleaning

25,00



Bumper F M, Scratch(es), It - Spot repair

115,00



Door R L, Dent(s), Acceptable

0,00



Trunk lid covering R, Scratch(es), Acceptable

0,00



Alloy rim F L, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80





Alloy rim R L, Scratch(es), I - Repair

100,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Mats, Hole, Acceptable

0,00



Seat cover F R, Stain, Cleaning

25,00



Alloy rim F R, Scratch(es), Acceptable

0,00




Outer door handle F L, Scratch(es), Acceptable

0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

366,35



Rear window, Not original part, Remove lettering

25,00



Tailgate, Scratch(es), Acceptable

0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

356,20

