


OPEL Insignia: 1JGC347

Vinnumber:	WOLGM8ER0E1181075	Versionname:	INSIGNIA BRE ecoFL.Business 120PK
First Registrationdate:	9/12/2014	Fiscalpower:	
Expertise Mileage:	187882	Power Kw:	88
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4212
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 4 mm	Re.R.	Kleber: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	481,50
-------------------	---------------


Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	---------------



Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy Rims (all), Rust, Acceptable	0,00
No pictures to display	