



VOLVO V90: BS7254

Vinnumber:	YV1PWA8BCJ1038766	Versionname:	D4 4x4 Geartronic Inscription
First Registrationdate:	1/06/2017	Fiscalpower:	
Expertise Mileage:	144663	Power Kw:	140
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2412
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

GPS storage	HD	Seats R heated	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/100 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1832,20
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	369,84



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R polished, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)

382,02



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L polished, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete)

382,02



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16

