



VOLKSWAGEN CADDY: 1JNL545

Vinnumber:	WV1ZZZ2KZEX127950	Versionname:	1.6 TDI 75KW VAN
First Registrationdate:	26/01/2015	Fiscalpower:	
Expertise Mileage:	213792	Power Kw:	75
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3226
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/92 H Steel			
Summer tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	982,68
-------------------	---------------

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	-------------

No pictures to display

Roof, Scratch(es), Acceptable	0,00
-------------------------------	-------------



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)



Trunk door R L, Dent(s), Acceptable 0,00

No pictures to display

Parking sensor R, Missing, E - Replace 5,00



Windscreen, Stone chip(s), E - Replace 395,40



Bumper R, Scratch(es), Smart repair 110,64



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 232,88



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display