


VOLVO V40: FP9119

Vinnumber:	VV1MVA8L1G2314674	Versionname:	2.0 D4 MOMENTUM
First Registrationdate:	4/12/2015	Fiscalpower:	
Expertise Mileage:	138967	Power Kw:	140
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3122
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	205/55/16/92 MS LightMetal			
	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2817,48
Wing R R, Dent(s), Acceptable	0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), Le - Replace and paint	735,00
---	---------------



Door F L, Dent(s), PDR - Paintless dent repair

63,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper grille, Broken, E - Replace

32,40



Rear window, Scratch(es), E - Replace

370,00



Alloy rim R L, Scratch(es), Acceptable

0,00

Any thin R, scratches, Acceptable	0,00
No pictures to display	
Sill outer R, Dent(s), Le - Replace and paint	712,00

