



VOLKSWAGEN POLO: 1JTG450

Vinnumber:	WVWZZZ6RZF247558	Versionname:	1.4 TDI 55KW TRENDLINE BMT
First Registrationdate:	19/02/2015	Fiscalpower:	
Expertise Mileage:	68899	Power Kw:	55
Bodytype:		Body color	Blue
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3523
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Central consol F
Radio multimedia	Luggage cover
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	Rear parking sensors
	Type of Tow bar
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

175/70/14/84 T Steel				
Summer tyres:	Fr.L.	Other: 3 mm	Fr.R.	Other: 3 mm
	Re.L.	Other: 3 mm	Re.R.	Other: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Total cost ex VAT	256,44
Door F R, Dent(s), PDR - Paintless dent repair	63,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Wheel cover F R, Scratch(es), E - Replace	24,00

