


SEAT ALHAMBRA: 1NFR245

Vinnumber:	VSSZZZ7NZGV715125	Versionname:	2.0 TDI 85KW STYLE ECOMOTIVE
First Registrationdate:	12/02/2016	Fiscalpower:	
Expertise Mileage:	109785	Power Kw:	85
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4624
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Sun Roof electric
GPS storage	Panoramic roof
GPS storage	SD Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/92 MS LightMetal				
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Total cost ex VAT	1144,35
Door R R, Dent(s), Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), LI - Repair and paint (complete)	382,02



Door F L, Dent(s), PDR - Paintless dent repair

63,00



Wing F R, Dent(s), PDR - Paintless dent repair

63,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)

348,09



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Wing F L, Dent(s), Acceptable

0,00

No pictures to display

Bumper grille, Broken, E - Replace

34,08



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Scratch(es), E - Replace

0,00

