



AUDI A3 SPORTBACK: 1RSD899

Vinnumber:	WAUZZZ8V9HA103504	Versionname:	1.6 TDi 81kW
First Registrationdate:	16/02/2017	Fiscalpower:	
Expertise Mileage:	31445	Power Kw:	81
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3628
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

205/55/16/92 MS LightMetal				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1538,63
Wing R R, Repaired, Acceptable			0,00



Bonnet, Chemical polution, 67 - Polish	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
 	
Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
 	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
 	
Door R R, Dent(s), LI - Repair and paint (complete)	318,35
 	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
 	
Roof, Chemical polution, LI - Repair and paint (complete)	481,50
 	