



Audi A1: 1TLK160

Vinnumber:	WAUZZZ8X5JB043982	Versionname:	
First Registrationdate:	7/12/2017	Fiscalpower:	
Expertise Mileage:	35991	Power Kw:	60
Bodytype:		Body color	Blue
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Petrol	Oil level	OK
Maintenance	OK	Parking lot	4302
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Luggage cover	
GPS storage	SD	Rear parking sensors	
GPS storage			
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/92 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1476,38
Bumper R, Scratch(es), LI - Repair and paint (complete)			169,44




Ignition key, Missing, E - Replace

150,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)

232,06



Alloy rim FL, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim FR, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim RR, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Chemical polution, LI - Repair and paint (complete)

385,20



Door FR, Chemical polution, LI - Repair and paint (complete)

254,68

