



BMW 4 GRAN COUPE: 1RBE745

Vinnumber:	WBA4E71000G746821	Versionname:	2.0 418D (100KW) GRAN COUPE
First Registrationdate:	3/11/2016	Fiscalpower:	
Expertise Mileage:	109979	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metallic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3106
Number of doors	5		
Number of seats	4		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Front parking sensors	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	No Tow bar
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/50/17/93 W LightMetal			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	205,64
Wing FR, Scratch(es), Acceptable	0,00



Door panel RL, Scratch(es), Smart repair

110,64



Door FL, Scratch(es), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00



Bumper FR, Repaired, Acceptable

0,00



Alloy rim FR, Scratch(es), LI - Repair and paint (complete)

95,00



Door FL, Dent(s), Acceptable

0,00

