


SKODA SUPERB: 1LGS729

Vinnumber:	TMBAG7NP4G7019795	Versionname:	1.6 CRTDI 88KW STYLE
First Registrationdate:	23/09/2015	Fiscalpower:	
Expertise Mileage:	87295	Power Kw:	88
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1305
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Seats R heated
Windows electric F	Seats electric F L
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	No Tow bar
Type of GPS	Headlighting Halogen
Type of Lining	GPS big screen color
Type of climate control	Lining fabrics
	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/55/17/94 V LightMetal			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			254,16
Bumper R, Scratch(es), LI - Repair and paint (complete)			254,16



Bumper F, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Door RR, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door RL, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing RR, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door FL, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	