



RENAULT Kangoo: 1AJL555

Vinnumber:	VF1KW04B544666703	Versionname:	KANGOO Authentique 75PK
First Registrationdate:	24/01/2011	Fiscalpower:	
Expertise Mileage:	39961	Power Kw:	55
Bodytype:		Body color	White
Gearbox:	MAN 5 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2404
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Luggage cover	
Windows electric F	Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	195/65/15/91 T Steel			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2484,26
-------------------	----------------

Roof, Deformed / Strained, LI - Repair and paint (complete)	481,50
---	---------------



Boot lid covering R, Scratch(es), E - Replace

86,40



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Wheel cover FL, Scratch(es), E - Replace 30,00



Wing RR, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Ignition key, Missing, E - Replace 150,00



Wheel cover RL, Scratch(es), E - Replace 30,00



Wing RL, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wheel cover RR, Scratch(es), E - Replace 30,00



Bumper F, Scratch(es), E - Replace 499,20



Wheel cover FR, Scratch(es), E - Replace 30,00



Bumper R, Scratch(es), E - Replace 415,20



Outside rear-view mirror housing R, Broken, E - Replace	115,56
---	--------



Door FL, Dent(s), Acceptable	0,00
------------------------------	------

No pictures to display