



VOLKSWAGEN CADDY: 1JTP912

Vinnumber:	WV1ZZZ2KZFX087559	Versionname:	1.6 TDI 55KW VAN
First Registrationdate:	23/02/2015	Fiscalpower:	
Expertise Mileage:	123290	Power Kw:	55
Bodytype:		Body color	White
Gearbox:	MAN 5 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2525
Battery functioning	Yes		
Number of doors	5		
Number of seats	2		
Number head rests	2		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Type of Tow bar	No Tow bar
Windows electric F		
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Total cost ex VAT	1421,81
-------------------	---------

Backrest cover FL, Hole, E - Replace	300,00
--------------------------------------	--------



Wheel cover FL, Missing, E - Replace

22,50



Interior, Damaged, Acceptable

0,00



Door FL, Deformed / Strained, LI - Repair and paint (complete)

238,76



Seat cover FL, Hole, E - Replace

300,00



Wing RR, Rust, LI - Repair and paint (complete)

231,15



Bumper R, Scratch(es), E - Replace

329,40

