



BMW X3: 1LNY351

Vinnumber:	WBAWZ310600F65885	Versionname:	2.0 SDRIVE18D (100KW)
First Registrationdate:	2/11/2015	Fiscalpower:	
Expertise Mileage:	141856	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Wheel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3125
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Seats electric F L
GPS storage	Seats electric F R
GPS storage	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/17/99 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	-----	------------	-----

Total cost ex VAT	178,56
Alloy rim RL, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), It - Spot repair	115,56



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door FR, Dent(s), PDR - Paintless dent repair	63,00
---	-------



Door RR, Dent(s), Acceptable	0,00
------------------------------	------

No pictures to display

Alloy rim FR, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display