



PEUGEOT 208: 1EAY107

Vinnumber:	VF3CC8HR0CT120085	Versionname:	208 BER Active 68PK
First Registrationdate:	8/10/2012	Fiscalpower:	
Expertise Mileage:	46430	Power Kw:	50
Bodytype:		Body color	Silver
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2701
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 MS Steel			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			677,40
Wheel cover FL, Scratch(es), E - Replace			24,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Bumper FL, Scratch(es), It - Spot repair

115,56



Wheel cover FR, Scratch(es), E - Replace

24,00



Outer sill L, Dent(s), LI - Repair and paint (complete)

344,40



Wing RL, Repaired, Acceptable

0,00



Bonnet, Increased paint layer, No repair

0,00



Wheel cover RR, Scratch(es), Acceptable

0,00

No pictures to display