


SKODA Octavia: 1JPP951

Vinnumber:	TMBJG7NEXF0126419	Versionname:	OCTAVIA COMBI Ambition 105PK
First Registrationdate:	2/02/2015	Fiscalpower:	
Expertise Mileage:	91835	Power Kw:	77
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4104
Maintenance:	OVER 19900 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Rear parking sensors
Windows electric F	Type of Tow bar
Windows electric R	Tow bar removable
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	205/55/16/91 H Steel			
	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Semperit: 6 mm	Re.R.	Semperit: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			891,89
Door FL, Scratch(es), LI - Repair and paint (complete)			318,35



Bumper R, Scratch(es), Acceptable

0,00



Wheel cover RR, Scratch(es), Acceptable

0,00



Wheel cover FR, Scratch(es), Acceptable

0,00



Bumper F, Dent(s), It - Spot repair

115,56



Door RR, Scratch(es), Acceptable

0,00



Engine protection plate, Hole, E - Replace

119,78



Wheel cover FL, Scratch(es), E - Replace

30,00



Wing RL, Scratch(es), LI - Repair and paint (complete)

308,20

