













115,56

HYUNDAI	GRAND	SANIA	FE:	15NK664

Vinnumber:	KMHSR81XDHU228071	Versionname:	2.2 CRDi 4x4 Aut. Executive
First Registrationdate:	14/06/2017	Fiscalpower:	
Expertise Mileage:	110237	Power Kw:	147
Bodytype:		Body color	Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	4 Weel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	ОК
Maintenance	ок	Parking lot	3209
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	ок		
Registration Certificate Car (BE)	Yes		

Options

GPS storage Seats R heated GPS storage SD Seats electric F L Windows electric F Seats electric F R Windows electric R Sun Roof electric Cruise Control Panoramic roof Steering wheel multifunctional Central consol F Seats F heated Luggage cover Radio multimedia Front parking sensors Type of headlighting Rear parking sensors **Headlighting Xenon** Type of GPS

GPS big screen color Type of Tow bar No Tow bar

Type of Lining Lining leather Type of climate control Autom climate control

Adaptive cruise control

Limited Technical Inspection

Airco functioning	ок	Battery functioning	Yes
Tires wear profile	ок	Power steering	Yes
Idle position	ок	Sound engine	ок
Engine startingtime	ок	Clutch test	ок
Exhaust gass	ок	Wiper fluid level	ок
Handbrake	ок	Transmission	ок
		Lighting	ок
		Winashladas	OIL

Degree of wear

	235/55/1	35/55/19/101 V LightMetal			
Winter tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm	
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm	

Assistance	eguinma	ant
Madiatuille	equipini	

Bumper FL, Scratch(es), It - Spot repair

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			695,84









Bumper spoiler F, Scratch(es), Acceptable	0,00
No pictures to display	
Wing RR, Scratch(es), It - Spot repair	115,56





Alloy rim FR polished, Scratch(es), LI - Repair and paint (complete)	
--	--





Door RR, Sci	eratch(es), It - Spot repair	115,56





Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16

95,00









