



Mazda CX3: 1WKR275

Vinnumber:	JMZDK6W7A01454951	Versionname:	
First Registrationdate:	26/06/2019	Fiscalpower:	
Expertise Mileage:	6727	Power Kw:	89
Bodytype:		Body color	White
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	2204
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/50/18/92 V LightMetal			
	Fr.L.	Toyo: 6 mm	Fr.R.	Toyo: 6 mm
	Re.L.	Toyo: 6 mm	Re.R.	Toyo: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			427,20
Lower door moulding RL, Scratch(es), E - Replace			114,00



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door RL, Dent(s), PDR - Paintless dent repair	63,00
---	-------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing moulding FR, Scratch(es), E - Replace	38,40
--	-------

